

SB 613552



Technical Information

Automatic Transmissions

24 75 00


Page 1 of 2

March 2000

Service Engineering

SUBJECT

E46 M52TU/B25 with ZF 5HP19 as of 3/2000 Production




MODEL

E46 - 323iA, 323iAT produced as of 3/2000

SITUATION

The ZF 5HP19 will be installed in the E46 323iA/iAT beginning with March 2000 production. The E46 328iA will continue to be manufactured with the GM 5L40E



S24 00 U03

Please initial and route to the following for information before filing

<input checked="" type="checkbox"/>	Service Manager	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Warranty	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Service Technicians - Initial Below			
<input checked="" type="checkbox"/>	Service Advisor	<input type="checkbox"/>	<input type="checkbox"/>	Parts Mgr.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	Service Advisor	<input type="checkbox"/>	<input type="checkbox"/>	Body Shop	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	Shop Foreman	<input type="checkbox"/>	<input type="checkbox"/>	PDI Dept.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

★ ★ **FIX IT RIGHT THE FIRST TIME, ON TIME, EVERY TIME** ★ ★

For administrative convenience and to reduce costs, this bulletin may contain repair procedures for authorized BMW car centers and/or authorized BMW SAV centers. All references to SAVs and/or the X5 are ONLY intended for authorized BMW SAV centers. Furthermore, ONLY BMW SAV centers are authorized to perform repair and service work on SAVs.